

<b>Title</b>	<b>Radioactive Materials Collection and Transport</b>
<b>Specimen Requirements</b>	<p>Samples for radioactive material testing must be submitted by a County Health Department, a State Agency, or a Federal Agency.</p> <p>Contact: Jane Smith: 317-921-5515 for further instructions.</p>
<b>Sampling Materials</b>	Sampling materials can vary widely depending upon the material that is to be sampled.
<b>Procedural Notes</b>	<p>Wipe Samples from Lead Paint Analyzers:  With 2 small plastic bags, sharpie marker, Lead Painter Analyzer and alcohol wipes to be used to obtain the sample, place an unused alcohol wipe in one of the plastic bags and mark the bag "Blank Wipe".</p> <p>The following information and an individual plastic bag for each Analyzer to be wiped is required:</p> <p>Location: Your County Health Dept. with contact information  Manufacture and model of the analyzer  Analyzer Unit Serial number  Source Isotope  Source Date  Source Activity on that date:</p> <p>Water Samples:  The volume required can vary and glass or plastic may be required for sample integrity to be maintained. Contact Jane Smith at 317-921-5515 and the proper sample container will be shipped to your facility.</p> <p>Unknowns Samples:  Contact: Jane Smith: 317-921-5515 for further instructions.</p>
<b>Shipping Instructions</b>	<p>Place sample(s) in an appropriate shipping container and ship or deliver to:</p> <p>Indiana State Department of Health Laboratories  Radiochemistry Laboratory  Attention: Jane Smith  550 W. 16th Street, Suite B  Indianapolis, IN 46202  317/921-5515,</p>
<b>Reporting and TAT</b>	Analyte dependent.